

Notes:

1) On 2005 models built before July 8, 2005 inspect primary adjustment shoe, per SB-1059

2) Inspect carrier bearing basket for cracks on all 2005 models.

