
TRANSMISSION NOISE
Is the correct amount of fluid present?
Yes
No
Add the correct amount of fluid.
Maintenance
Is the noise a grind or gear noise?
Yes
No
Perform SB-1090 Countershaft Washer Replacement. (2005-2006 models built before July 22, 2006)
SB-1090
Is there a squeal noise when disengaging the clutch?
Yes
No
Perform SB-1065A Clutch Pushrod Replacement. (2005-2006 models built before March 23, 2006)
SB-1065A
Call Tech Support.